



FACTORY MACHINERY LAYOUT

1	CIRCULAR COLD SAW	6	6.3 TON OVERHEAD CRANE	11	AIR COMPRESSOR	16	WELDING GANTRY		
2	DRILL	7	PEDDIMASTER	12	16.0 TON OVERHEAD CRANE	17	BLASTING ROOM		
3	GUILLOTINE SHEAR	8	IRON WORKER	13	FLAME PLANNER				
4	PRESS BRAKER	9	AIR COMPRESSOR	14	ASSEMBLY MACHINE				
5	PLATE ROLLER	10	AIR COMPRESSOR	15	STRAIGHTENING MACHINE				